Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Melvin Benally No. 1 AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

August 2010

Part I	Site Identification, Location and Status				
Site Names ar	nd ID numbers as applicable				
Mine ID:	622				
Map ID:	N53				
CERCLIS:	NNN000909027				
Navajo Abano	doned Mine Land Reclamation Program: NA-0506				
Local name /	Aliases: Melvin Benally 1; Benally; Marvin Benally #1; Benally No. 1				
Chapter and local area: Sweetwater Chapter					
County: Apac	Apache State: Arizona				
Lat/Long: 36.828307523 N / -109.266779115 W					
Nearby road and highway: Highway 160 Local Post Office: Teec Nos Pos					
Surface Land Status: check one or more and provide ownership and contact information below					
Tribal Trust l Private Bureau of Las State	Tribal Fee Land				
Subsurface M	fineral Rights:				
No information on subsurface mineral rights ownership was found in the EPA/AUM Database.					
Claim and op	perator information:				
the operator of	surface land status is classified as Tribal Trust Land. Historical documents showed f the mine as Byden Mines in 1955. No other historical ownership / lease as identified in the EPA/AUM database.				
Number of residential structures within 200 feet of mine: None					

Estimated volume of mine waste onsite: None

Part II Summary of radiological readings

Highest gamma radiation measurement:

105408 counts per minute (cpm)

Describe any other radiological measurements:

A total of 1421 gamma radiation measurements were collected from the mine site, ranging from 7879 cpm to 105408 cpm. Measurements collected in the vicinity of the workings were found at levels up to approximately 105,000 cpm. The measurements are represented in Figures 1 and 2.


Background Locations

Average background = 11,275 cpm

#1 11,275 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1421

 Minimum:
 7879.00000

 Maximum:
 105408.00000

 Sum:
 25561415.00000

 Mean:
 17988.32864

 Median:
 13002.00000

 Standard Deviation:
 14321.31390

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0506

NAMLRP Mine features: 1 Portal

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work and	status
Obstived	1 CCIamanon	wuin anu	status.

Adits

None

Waste Piles

None

Pits

Possible excavation pit

Shafts

None

Other Debris and Mine Features

Assorted mine workings evidence

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: Surface water stream heading SW through site

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

Horses onsite

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Melvin Benally No. 1 mine consists of an area of 2,481.4 m². The mine was identified as being operational in 1955. Historical documents showed the operator of the mine as Byden Mines in 1955. While operational, the mine had a total reported production volume of 81 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Melvin Benally No. 1 **Chapter:** Sweetwater

Decision Criteria

Is there an unreclaimed waste pile at the site? No

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? None

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

Possible excavation pit

Part VI Photos



Photo 1. Melvin Benally No. 1 site




Photo 2. Melvin Benally No. 1 site



Photo 3. Melvin Benally No. 1 site

Name:

Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331					
Title or official role (if any) Navajo EPA Superfund Program					
AddressPO Box 2946, Window Rock, AZ 86515					
Information provided <u>Lead Regulatory Agency</u>					
Name					
Title or official role (if any)					
Telephone number					
Information provided					
Name	_				
Title or official role (if any)					
Telephone number					
Information provided					
Name	_				
Title or official role (if any)					
Telephone number					
Information provided					

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Melvin Benally No. 1 (622)
Sweetwater Chapter, Navajo Nation





Figure 2 - Gamma Radiation Measurements Melvin Benally No. 1 (622) Sweetwater Chapter, Navajo Nation



Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- **15,000 20,000**
- 20,000 50,000
- 50,000 100,000
- > 100,000

→ General Direction Down-Slope

Mine Claim Boundaries

Gamma survey conducted 06/2010 Measured as counts per minute (cpm)

Average background 11,275 cpm

